

## 1999 ARRL Handbook Drawing Correction, Chapter 13

In *The 1999 ARRL Handbook for Radio Amateurs*, the power supply diagram on page 13.33 (figure 13.34) contains errors. Diodes D9 and D10 are drawn with reverse polarity. This [corrected schematic](#) has them drawn correctly.

Copyright © 1998 by The American Radio Relay League, Inc.

*Copyright secured under the Pan-American Convention*

International Copyright secured

This work is Publication no. 6 of the Radio Amateur's Library, published by the League. All rights reserved. No part of this work may be reproduced in any form except by written permission of the publisher. All rights of translation are reserved.

Printed in the USA

*Quedan reservados todos los derechos*

Library of Congress Catalog Card Number: 55-8966

76th Edition

ISBN: 0-87259-181-6

