

1999 ARRL Handbook Drawing Correction, Chapter 24

In *The 1999 ARRL Handbook for Radio Amateurs*, the Op Amp ICs table on page 24.26-24.27 includes several schematics which are incorrect. The corrected schematics are on the [following page](#).

Copyright © 1998 by The American Radio Relay League, Inc.

Copyright secured under the Pan-American Convention

International Copyright secured

This work is Publication no. 6 of the Radio Amateur's Library, published by the League. All rights reserved. No part of this work may be reproduced in any form except by written permission of the publisher. All rights of translation are reserved.


Printed in the USA

Quedan reservados todos los derechos


Library of Congress Catalog Card Number: 55-8966

76th Edition


ISBN: 0-87259-181-6




386




555




556




LM747CN
MC1747CP2
 μ A747PC




MC1458CP1
LF353N
N5558V
LM1458N
LM358N
 μ A1458TC
SK3465
ECG778




μ A324PC
 μ A348PC
LM24N
LM348N
TL084CN




ECG431M
LF356N
MC1741CP1
 μ AF356TC
LM741CN
 μ A741TC



CA314DE



LM709CN -8
MC1709CP -1
SK 3590
ECG909



NE5534N