

```
/*
```

```
Modified to output to 16 x 2 LCD Display - Glen Popiel KW5GP
```

```
Based on HMC5883L_Example.pde - Example sketch for integration with an  
HMC5883L triple axis magnetometer. Copyright (C) 2011 Love Electronics  
(loveelectronics.co.uk)
```

```
This program is free software: you can redistribute it and/or modify  
it under the terms of the version 3 GNU General Public License as  
published by the Free Software Foundation.
```

```
This program is distributed in the hope that it will be useful,  
but WITHOUT ANY WARRANTY; without even the implied warranty of  
MERCHANTABILITY or FITNESS FOR A PARTICULAR PURPOSE. See the  
GNU General Public License for more details.
```

```
You should have received a copy of the GNU General Public License  
along with this program. If not, see <http://www.gnu.org/licenses/>.
```

```
*/
```

```
#include <Wire.h> // Use the I2C Library  
#include <HMC5883L.h> // Use the HMC5883L Compass Library  
#include <LiquidCrystal_I2C.h> // Use the Liquid Crystal I2C Library
```

```
const int lcd_end = 16; // set width of LCD  
const int lcd_address = 0x27; // I2C LCD Address  
const int lcd_lines = 2; // Number of lines on LCD
```

```
HMC5883L compass; // Store our compass as a variable.  
int error = 0; // Record any errors that may occur in the compass.  
String Direction; // Store the Direction Text as a variable
```

```
// set the LCD I2C address to 0x27 for a 16 chars and 2 line display  
LiquidCrystal_I2C lcd(lcd_address,lcd_end,lcd_lines);
```

```
void setup()
```

```
{  
  Wire.begin(); // Start the I2C interface.  
  
  lcd.init(); // initialize the LCD  
  lcd.backlight(); // Turn on the LCD backlight  
  lcd.home(); // Set the cursor to line 0, column 0  
  
  compass = HMC5883L(); // Construct a new HMC5883 compass.  
  
  error = compass.SetScale(1.3); // Set the scale of the compass to +/-  
1.3Ga.  
  if(error != 0) // If there is an error, print it out.  
  {  
    error = compass.SetMeasurementMode(Measurement_Continuous); // Set  
the measurement mode to Continuous  
  }  
}
```

```

} // End Setup Loop

void loop()
{
    // Retrieve the raw values from the compass (not scaled).
    MagnetometerRaw raw = compass.ReadRawAxis();

    // Retrieved the scaled values from the compass (scaled to the
    configured scale).
    MagnetometerScaled scaled = compass.ReadScaledAxis();

    // Values are accessed like so:
    int MilliGauss_OnThe_XAxis = scaled.XAxis; // (or YAxis, or ZAxis)

    // Calculate heading when the magnetometer is level, then correct for
    signs of axis.
    float heading = atan2(scaled.YAxis, scaled.XAxis);

    // Once you have your heading, you must then add your 'Declination
    Angle', which is the 'Error' of the magnetic field in your location.
    // Find yours here: http://www.magnetic-declination.com/

    // If you cannot find your Declination, comment out these two lines,
    your compass will be slightly off.
    float declinationAngle = 0.0169296937; // Declination for Southaven,
    MS
    heading += declinationAngle;

    if(heading < 0) // Correct for when signs are reversed.
    {
        heading += 2*PI;
    }

    if(heading > 2*PI) // Check for wrap due to addition of declination.
    {
        heading -= 2*PI;
    }

    float headingDegrees = heading * 180/M_PI; // Convert radians to
    degrees for readability.

    Output(raw, scaled, heading, headingDegrees); // Output the data to
    the LCD

    delay(1000); // Update the LCD every second
}

// Output the data to the LCD
void Output(MagnetometerRaw raw, MagnetometerScaled scaled, float
heading, float headingDegrees)
{
    lcd.clear();

```

```

lcd.print("^  "); // Print an up arrow to indicate compass pointer
lcd.print(headingDegrees,1); // Display the Heading in degrees
lcd.print(" Deg");
lcd.setCursor(15,0);
lcd.print("^");

// Calculate Direction
Direction = " ";
lcd.setCursor(6,1);

if (headingDegrees >= 348.75 | headingDegrees <11.25) // Direction =
North
{
    Direction = " N";
}
if (headingDegrees >= 11.25 && headingDegrees <33.75) // Direction =
North North East
{
    Direction = "NNE";
}
if (headingDegrees >= 33.75 && headingDegrees <56.25) // Direction =
North East
{
    Direction = "NE";
}
if (headingDegrees >= 56.25 && headingDegrees <78.75) // Direction =
East North East
{
    Direction = "ENE";
}
if (headingDegrees >= 78.75 && headingDegrees <101.25) // Direction =
East
{
    Direction = " E";
}
if (headingDegrees >= 101.25 && headingDegrees <123.75) // Direction =
East South East
{
    Direction = "ESE";
}
if (headingDegrees >= 123.75 && headingDegrees <146.25) // Direction =
South East
{
    Direction = "SE";
}
if (headingDegrees >= 146.25 && headingDegrees <168.75) // Direction =
South South East
{
    Direction = "SSE";
}
if (headingDegrees >= 168.75 && headingDegrees <191.25) // Direction =
South
{
    Direction = " S";
}

```

```

    }
    if (headingDegrees >= 191.25 && headingDegrees <213.75) // Direction =
South South West
    {
        Direction = "SSW";
    }
    if (headingDegrees >= 213.75 && headingDegrees <236.25) // Direction =
South West
    {
        Direction = "SW";
    }
    if (headingDegrees >= 236.25 && headingDegrees <258.75) // Direction =
West South West
    {
        Direction = "WSW";
    }
    if (headingDegrees >= 258.75 && headingDegrees <281.25) // Direction =
West
    {
        Direction = " W";
    }
    if (headingDegrees >= 281.25 && headingDegrees <303.75) // Direction =
West North West
    {
        Direction = "WNW";
    }
    if (headingDegrees >= 303.75 && headingDegrees <326.25) // Direction =
North West
    {
        Direction = "NW";
    }
    if (headingDegrees >= 326.25 && headingDegrees <348.75) // Direction =
North North West
    {
        Direction = "NNW";
    }

    lcd.print(Direction); // Display the direction on the LCD
}

```